

HUBER/SUHNER

HUBER/SUHNER #	SOLITRON #
11 SMA 50 2-5C	2903-6001
11 SMA 50 2-15	2906-6002
11 SMA 50 2-55C	2903-6001
11 SMA 50 3-6C	2900-6001
11 SMA 50 3-7C	2900-6002
11 SMA 50 3-8C	2900-6001
11 SMA 50 3-10C	2900-6002
11 SMA 50 3-14	2902-6007
11 SMA 50 3-15	2902-6005
11 SMA 50 3-16	2902-6001
11 SMA 50 3-55	2900-6001
11 SMA 50 3-56C	2942-6035
13 SMA 50 0-1	2955-6002
13 SMA 50 0-6	2955-6017
13 SMA 50 0-11	2955-6030
13 SMA 50 0-38	2955-6033
13 SMA 50 0-39	2955-6095
13 SMA 50 0-51	2955-6022
13 SMA 50 0-61	2955-6030
13 SMA 50 0-88	2955-6003
23 SMA 50 0-1	2950-6081
23 SMA 50 0-2	2983-6001
23 SMA 50 0-3	2950-6061
23 SMA 50 0-5	2950-6002
23 SMA 50 0-6	2950-6106
23 SMA 50 0-11	2950-6062
23 SMA 50 0-12	2950-6043
23 SMA 50 0-13	2950-6200
23 SMA 50 0-15	2950-6199
23 SMA 50 0-17	2950-6042
23 SMA 50 0-22	2950-6135
23 SMA 50 0-23	2950-6136
23 SMA 50 0-51	SF 2950-6081
23 SMA 50 0-52	SF 2950-6045
23 SMA 50 0-53	2950-6061
23 SMA 50 0-54	2950-6062
23 SMA 50 0-61	SF 2950-6043
23 SMA 50 0-62	2950-6200
24 SMA 50 2-15	2946-6012
24 SMA 50 3-7C	2941-6030
24 SMA 50 3-8C	2941-6030
24 SMA 50 3-10C	2941-6030
24 SMA 50 3-15	2942-6004
25 SMA 50 2-5C	2931-6009
25 SMA 50 2-15	2933-6004
25 SMA 50 2-25	2933-6001
25 SMA 50 3-5C	2931-6012
25 SMA 50 3-6C	2931-6012
25 SMA 50 3-15	2932-6001
25 SMA 50 3-25	2912-6001
29 SMA 50 0-1	2960-6001
31 SMA 50 0-1	2992-6001
32 SMA 50 0-1	2993-6001
34 SMA 50 0-1	2990-6005

HUBER/SUHNER #	SOLITRON #
----------------	------------